

Electronic Meter

User Manual



Manuel d'utilisation

(pH) FT11

Manual de usuario

(TDS) FT34 FT36

Gebrauchsanleitung


(EC) FT33 FT35

Manuale dell'utente




	FT11	FT34	FT36	FT33	FT35
Range	0.0-14.0 pH	0-1999 ppm 0.0-1.999 ppt)	(0-10000 ppm) 0.00-10.00 ppt	0-1999 μ S/cm (0-1.999 mS/cm)	(0-19990 μ S/cm) 0.00 - 19.99 mS/cm
Resolution	0.1 pH	1 ppm	0.01 ppt	1 μ S/cm	0.01 mS/cm
Accuracy	+/- 0.1 pH	+/- 2% FS	+/- 2% FS	+/- 2% FS	+/- 2% FS
Calibration	manual	manual	manual	manual	manual
Temp. Comp.		automatic 0 - 50° C β = 2%/°C	automatic 0 - 50° C β = 2%/°C	automatic 0 - 50° C β = 2%/°C	automatic 0 - 50° C β = 2%/°C
Battery Type	3 x 1.5 V	4 x 1.5 V	4 x 1.5 V	4 x 1.5 V	4 x 1.5 V
Batt. Life	~ 1000 h	~250 h	~250 h	~250 h	~250 h
Environment	0 - 50° C RH 100%	0 - 50° C RH 100%	0 - 50° C RH 100%	0 - 50° C RH 100%	0 - 50° C RH 100%

Calibration



Use



Battery

